

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S64	9	("3767915" "4788432" "6204516" "6211692").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S65	77	250/370.02.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:33
S66	55815	sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S67	6805	S66 and (radiation or cosmic or alpha or gamma)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:34
S68	3409	S67 and (ser or soft adj error adj rate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S69	1	S68 and redundancy adj repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S70	2	S66 and redundancy adj repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S71	2	S66 and repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S72	106	S66 and repair same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S73	8	S68 and repair same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S74	55815	sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S75	560	S74 and (radiation or cosmic or alpha or gamma).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51

S76	77	250/370.02.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S77	55815	sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S78	6805	S74 and (radiation or cosmic or alpha or gamma)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S79	3409	S78 and (ser or soft adj error adj rate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S80	2	S74 and repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S81	1	S79 and redundancy adj repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S82	9	("3767915" "4788432" "6204516" "6211692").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S83	2	S74 and redundancy adj repair adj latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S84	8	S79 and repair same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S85	106	S74 and repair same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S86	560	S74 and (radiation or cosmic or alpha or gamma).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S87	220	S86 and S79	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S88	18	S87 and repair	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51

S89	3782	S78 and (ser or soft adj error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S90	313	S86 and S89	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S91	892	S78 and (soft adj error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S92	163	S86 and S91	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S93	55815	sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S94	6805	S93 and (radiation or cosmic or alpha or gamma)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S95	560	S93 and (radiation or cosmic or alpha or gamma).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S96	892	S94 and (soft adj error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S97	163	S95 and S96	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S98	38	(US-20030107913-\$ or US-20030205766-\$ or US-20030227788-\$ or US-20030234430-\$ or US-20040009639-\$ or US-20040030956-\$ or US-20040061060-\$ or US-20040124876-\$ or US-20040187050-\$ or US-20050012045-\$ or US-20050027409-\$ or US-20050040844-\$ or US-20050078543-\$ or US-20050127971-\$).did. or (US-3767915-\$ or US-4788432-\$ or US-4956815-\$ or US-5048023-\$ or US-5303190-\$ or US-5631863-\$ or US-6058041-\$ or US-6104211-\$ or US-6204516-\$ or US-6211692-\$ or US-6271568-\$ or US-6326809-\$ or US-6507511-\$ or US-6583470-\$ or US-6807081-\$ or US-6828561-\$ or US-6838899-\$ or US-6873565-\$ or US-6909159-\$ or US-6924995-\$).did. or (WO-9934368-\$).did. or (JP-2005116164-\$).did. or (US-5821136-\$ or US-20030107913-\$).did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S99	6805	S93 and (radiation or cosmic or alpha or gamma)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51

S10 0	134	S99 and single adj event	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 1	277	S97 S100	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 2	210	S101 and (clock\$4 timing time)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 3	58	S101 and (redund\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 4	119	S101 and (latch\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 5	135	S101 and (active)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 6	12	S101 and (repair)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 7	12	S101 and (repair\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 8	109	S101 and detect\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S10 9	10	S101 and (reload)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S11 0	73	S101 and strike	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S11 1	101	S102 and S108	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S11 2	43	S111 and S103	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51

S11 3	14	S101 and ECC	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S11 4	44	(US-20030107913-\$ or US-20030205766-\$ or US-20030227788-\$ or US-20030234430-\$ or US-20040009639-\$ or US-20040030956-\$ or US-20040061060-\$ or US-20040124876-\$ or US-20040187050-\$ or US-20050012045-\$ or US-20050027409-\$ or US-20050040844-\$ or US-20050078543-\$ or US-20050127971-\$ or US-20040148069-\$ or US-20040078103-\$ or US-20050050386-\$ or US-20050076274-\$ or US-20040210728-\$ or US-20040148559-\$).did. or (US-3767915-\$ or US-4788432-\$ or US-4956815-\$ or US-5048023-\$ or US-5303190-\$ or US-5631863-\$ or US-6058041-\$ or US-6104211-\$ or US-6204516-\$ or US-6211692-\$ or US-6271568-\$ or US-6326809-\$ or US-6507511-\$ or US-6583470-\$ or US-6807081-\$ or US-6828561-\$ or US-6838899-\$ or US-6873565-\$ or US-6909159-\$ or US-6924995-\$).did. or (WO-9934368-\$).did. or (JP-2005116164-\$).did. or (US-5821136-\$ or US-20030107913-\$).did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/13 15:51
S11 5	44	(US-20030107913-\$ or US-20030205766-\$ or US-20030227788-\$ or US-20030234430-\$ or US-20040009639-\$ or US-20040030956-\$ or US-20040061060-\$ or US-20040078103-\$ or US-20040124876-\$ or US-20040148069-\$ or US-20040148559-\$ or US-20040187050-\$ or US-20040210728-\$ or US-20050012045-\$ or US-20050027409-\$ or US-20050040844-\$ or US-20050050386-\$ or US-20050076274-\$ or US-20050078543-\$ or US-20050127971-\$).did. or (US-3767915-\$ or US-4788432-\$ or US-4956815-\$ or US-5048023-\$ or US-5303190-\$ or US-5631863-\$ or US-6058041-\$ or US-6104211-\$ or US-6204516-\$ or US-6211692-\$ or US-6271568-\$ or US-6326809-\$ or US-6507511-\$ or US-6583470-\$ or US-6807081-\$ or US-6828561-\$ or US-6838899-\$ or US-6873565-\$ or US-6909159-\$ or US-6924995-\$).did. or (WO-9934368-\$).did. or (JP-2005116164-\$).did. or (US-5821136-\$ or US-20030107913-\$).did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/13 17:53
S11 6	38	S115 and voltage	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 17:53
S11 7	12	S115 and voltage same well	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:03
S11 8	1536983	(radiation or cosmic or alpha or gamma)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:35
S11 9	199690	S118 and silicon	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:34
S12 0	108420	(radiation or cosmic or alpha or gamma) near4 (detect\$5 sens\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:37

S12 1	937	S120 and active same switching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:37
S12 2	5	S120 and non-active same switching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:37
S12 3	42675	(radiation or cosmic or alpha or gamma) near4 (detect\$5 sens\$4).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:51
S12 4	361	S123 and latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:39
S12 5	71	S123 and silicon and latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:52
S12 6	12	S123 and float\$4 near3 volt\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:41
S12 7	11	S123 and float\$4 near3 volta\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:41
S12 8	78971	(radiation or cosmic or alpha or gamma) same (detect\$5 sens\$4).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/13 18:51
S12 9	129	S128 and silicon and latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 12:42
S13 0	15	"590805"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 12:54
S13 1	20	"590806"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 12:56
S13 2	22	"590809"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 12:55
S13 3	4	("4144490" "5294843" "5589708" "5748412").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/14 12:55

S13 4	5	("4803592" "5107139" "5774321" "6005303" "6140806"). PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/14 12:57
S13 5	54	(US-20030107913-\$ or US-20030205766-\$ or US-20030227788-\$ or US-20030234430-\$ or US-20040009639-\$ or US-20040030956-\$ or US-20040061060-\$ or US-20040078103-\$ or US-20040124876-\$ or US-20040148069-\$ or US-20040148559-\$ or US-20040187050-\$ or US-20040210728-\$ or US-20050012045-\$ or US-20050027409-\$ or US-20050040844-\$ or US-20050050386-\$ or US-20050076274-\$ or US-20050078543-\$ or US-20050127971-\$ or US-20040200968-\$ or US-20050001171-\$ or US-20050005203-\$ or US-20040227094-\$ or US-20020180511-\$).did. or (US-3767915-\$ or US-4788432-\$ or US-4956815-\$ or US-5048023-\$ or US-5303190-\$ or US-5631863-\$ or US-6058041-\$ or US-6104211-\$ or US-6204516-\$ or US-6211692-\$ or US-6271568-\$ or US-6326809-\$ or US-6507511-\$ or US-6583470-\$ or US-6807081-\$ or US-6828561-\$ or US-6838899-\$ or US-6873565-\$ or US-6909159-\$ or US-6924995-\$ or US-6847040-\$ or US-6665161-\$ or US-6888398-\$ or US-6794733-\$ or US-6441440-\$).did. or (WO-9934368-\$).did. or (JP-2005116164-\$).did. or (US-5821136-\$ or US-20030107913-\$).did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/14 13:02
S13 6	37	S135 and alpha	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 13:14
S13 7	4	S135 and start-up	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 13:14
S13 8	3	S135 and startup	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 13:14
S13 9	6	S137 S138	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 13:16
S14 0	0	S135 and claock same low	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:39
S14 1	8	S135 and clock same low	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:43
S14 2	5	S135 and clock same cmos	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:45
S14 3	22	S135 and clock	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:52

S14 4	2	S135 and repair\$4 same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:53
S14 5	1	S135 and repair\$4 and (reload\$4 or refresh\$4) same latch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:53
S14 6	5	S135 and repair\$4 and (reload\$4 or refresh\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:56
S14 7	714	sram and repair\$4 and (reload\$4 or refresh\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:56
S14 8	45	sram and (repair same latch) and repair\$4 and (reload\$4 or refresh\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 15:57
S14 9	44	sram and (repair same latch) and repair\$4 and (reload\$4 or refresh\$4) and redundant\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:03
S15 0	1	sram and (repair same latch) and repair\$4 and (reload\$4 or refresh\$4) and seu	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:04
S15 1	2	sram and (repair same latch) and repair\$4 and (reload\$4 or refresh\$4) and (seu or soft adj error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:04
S15 2	32	sram and repair\$4 and (reload\$4 or refresh\$4) and (seu or soft adj error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:25
S15 9	14	sram and repair\$4 and (reload\$4 or refresh\$4) and (seu or soft adj error) and latch\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:28
S16 0	321	redundant\$4 same repair\$4 same latch\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:29
S16 1	2	redundant\$4 same repair\$4 adj latch\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:30
S16 2	321	redundant\$4 same repair\$4 same latch\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:32

S16 3	118	S162 and sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:31
S16 4	39	redundan\$4 near2 latch\$4 same repair	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:33
S16 5	12	redundan\$4 near2 latch\$4 same repair and sram	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 16:41
S16 6	2	"6829176".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 18:28
S16 7	5	"044242"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 18:29
S16 8	58	(US-20030107913-\$ or US-20030205766-\$ or US-20030227788-\$ or US-20030234430-\$ or US-20040009639-\$ or US-20040030956-\$ or US-20040061060-\$ or US-20040078103-\$ or US-20040124876-\$ or US-20040148069-\$ or US-20040148559-\$ or US-20040187050-\$ or US-20040210728-\$ or US-20050012045-\$ or US-20050027409-\$ or US-20050040844-\$ or US-20050050386-\$ or US-20050076274-\$ or US-20050078543-\$ or US-20050127971-\$ or US-20040200968-\$ or US-20050001171-\$ or US-20050005203-\$ or US-20040227094-\$ or US-20020180511-\$ or US-20040214389-\$).did. or (US-20030226074-\$).did. or (US-3767915-\$ or US-4788432-\$ or US-4956815-\$ or US-5048023-\$ or US-5303190-\$ or US-5631863-\$ or US-6058041-\$ or US-6104211-\$ or US-6204516-\$ or US-6211692-\$ or US-6271568-\$ or US-6326809-\$ or US-6507511-\$ or US-6583470-\$ or US-6807081-\$ or US-6828561-\$ or US-6838899-\$ or US-6873565-\$ or US-6909159-\$ or US-6924995-\$ or US-6847040-\$ or US-6665161-\$ or US-6888398-\$ or US-6794733-\$ or US-6441440-\$ or US-6829176-\$).did. or (US-6879530-\$).did. or (WO-9934368-\$).did. or (JP-2005116164-\$).did. or (US-5821136-\$ or US-20030107913-\$).did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/14 19:41
S16 9	53	S168 and well	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 19:42
S17 0	3	S168 and well near2 silicon	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/09/14 19:45